



**ULTRA** Analytix™

# Non-Intrusive & Non-Destructive Inspection of FRP – Case Studies

Geoff Clarkson, P.Eng.  
Chief Engineer, UTComp

# Plan

1. Introduction
2. Case Studies:
  - a) Duct
  - b) Vacuum Vessel
  - c) Spent Acid Tank
  - d) Dual Laminate
3. Summary



# Mechanical Integrity & Fitness for Service of FRP

## *Can the asset continue functioning?*


### ▶ Requires:

- Non-Destructive Methods
  - Repeatable and reliable
  - Current condition of a component
- Objective criteria for evaluation
  - Supported by data

### ▶ Desirable:

- Non-Intrusive Methods
  - Facility operating during inspection
  - Maximize safety of personnel
- Codes, Standards
  - Consensus standards linked to design – not available yet


**Purpose:** Provide meaningful Fitness for Service (FFS) and condition assessment of FRP.



Non-destructive & Non-intrusive




**Purpose:** Provide meaningful Fitness for Service (FFS) and condition assessment of FRP.




Non-destructive & Non-intrusive

# Parameters Used


- ▶ PDS: a parameter related to structural capacity



- ▶ Thickness:



- ▶ Corrosion Barrier Damage Depth



- ▶ Limits: based on experience derived from data
- ▶ *All derived from ultrasonic A-Scan*


# External FRP FFS Inspection

## ► Finds immediate issues

- *100% NON-INTRUSIVE*
- Identifies failures and problems visible from the outside
  - Leaks
  - Failed Flanges
  - Support defects
  - Overflow defects
  - Etc.
- Follow systematic checklist
- Some guidance from API 653, 510, 570



# How it Works



4  
RECEIVE  
REPORT

1  
COLLECT  
DATA IN FIELD

2  
COMPILE  
DATA

3  
TRANSMIT  
TO UTCOMP


Systematic  
Successful Training

Local Inspectors



Non Destructive  
Ultrasonic Readings  
External visual  
Non Intrusive  
No downtime

# When Data from New FRP is Not Available

- ▶ Assume that new FRP was at 100% of original design values.
  - ▶ Compare current values to 100%.
  - ▶ Track changes and predict life from fastest rate of change.
  - ▶ Calibration standards are NOT required.
- 



# Case Studies

# Case Study – SO<sub>2</sub> Duct

- ▶ Carrying corrosive humid SO<sub>2</sub> .
- ▶ Includes FRP expansion joints.
- ▶ Portions relined 2 years previously.
- ▶ Immediate replacement recommended at last internal inspection.
- ▶ “How soon do we need to replace?”




# Case Study – SO<sub>2</sub> Duct

- ▶ Inspection:
  - Completed while facility was operating.
  - Duct outer surface temperature ~ 75C.
  - All inspection of 1,000m of duct completed in 3 days.



# Case Study – SO<sub>2</sub> Duct

## ► Results:



# Case Study – SO<sub>2</sub> Duct

## ▶ Results:

- No need to replace 78" duct for foreseeable future.
- Expansion joints show structural damage.
- No damage to corrosion barrier was detected.



# Case Study – Vacuum Vessel

- ▶ First inspection in 2009.
- ▶ In 2010 low structural strength was noted.
- ▶ 2011 engineering analysis and repair recommended.




# Case Study – Vacuum Vessel

- ▶ March 2014: Design of repairs complete and planned for May



# Case Study – Vacuum Vessel

## ► Inspection History



# Case Study – Vacuum Vessel

- ▶ Results;
  - Timely identification of need for repair.
  - When completed, re-start life prediction.



# Case Study – Regenerated Acid Tank

- ▶ Pickling Acid
- ▶ 7 years old
- ▶ First inspection 2015 – ultrasonic
- ▶ Results show blisters in corrosion barrier and good structural capacity (57%; Safety factor 5.7)
- ▶ No thickness loss, no CB damage
- ▶ Several nozzles with cracked flanges





# Case Study – Regenerated Acid Tank

## Recommendations

- ▶ Replace damaged flanges
- ▶ Inspect again in 3 years

# Case Study – Regenerated Acid Tank

- ▶ Flanges were replaced.
- ▶ Corrosion barrier appearance:
  - Blisters as predicted
  - No significant softening
  - UT does not see color change but does see damage depth such as from softening, overheating
- ▶ Put back into service.



# Case Study – Dual Laminate

- ▶ Tanker:
  - Hand Layup using Novolac Resin
  - Lining: 2mm ETFE
- ▶ 22 years old
- ▶ Waste acid



# Case Study – Dual Laminate

- ▶ Stains and “bleed out” at some lining welds
- ▶ \$\$ available to repair BUT.....
- ▶ Must assess for fitness for service.





# Case Study – Dual Laminate

## ► Inspection and Results

PDS = 60%



PDS = 50%

PDS = 80%

PDS = 82%



PDS = 84%

PDS = 48%


## ► No damage to inner surface was detected



# Case Study – Dual Laminate


## Results:

- ▶ No damage to FRP detected under stained welds
- ▶ No significant structural damage to FRP at carriage




- ▶ Customer chose to return to service.
- ▶ Avoided ALL lining repair cost

# Limitations

- ▶ Operates best at temperatures  $>50^{\circ}\text{F}$  or  $10^{\circ}\text{C}$
  - ▶ Not useable with foam cores
  - ▶ Not useable with balsa core  $>3\text{inch}$  or  $7.5\text{cm}$
  - ▶ No verification for pipe  $<5\text{cm}$  ( $2\text{inch}$ ) outside diameter
  - ▶ High Magnetic fields disrupt instruments
  - ▶ Transducer must be in contact with FRP surface
  - ▶ Accurate interpretation in the field is not available
  - ▶ Scanning method has not been developed
- 

# Summary

- ▶ Safety: Significant reduction in Confined Space Entries.
  - ▶ Uptime: Evaluations are usually completed while operating.
  - ▶ ROI: Average savings \$10 – \$100 for each \$1 spent on this inspection.
- 
- ▶ Extensive history of valid and reliable results.
  - ▶ Meaningful FFS results.
- 

# Questions?

*Geoff Clarkson or Jo Anne Watton*

519-620-0772  
[inquiries@utcomp.ca](mailto:inquiries@utcomp.ca)



CELEBRATING 10 YEARS  
OF FRP RELIABILITY  
**INNOVATION**

